PHILIPS
100 Craftway Dr.
Littlestown, Pennsylvania 17340-0128
Phone: 717-359-7131

INSTALLATION INSTRUCTIONS: HANGING CEILING MOUNT FIXTURES

THIS PRODUCT MUST BE INSTALLED IN ACCORDANCE WITH THE APPLICABLE INSTALLATION CODE BY A PERSON FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT AND THE HAZARDS INVOLVED.

1. BEFORE BEGINNING TURN OFF POWER AT CIRCUIT BREAKER.
2. ATTACH MOUNTING CROSSBAR B TO OUTLET BOX A USING SCREWS C.
3. SCREW STUD D INTO THREADED HOLE OF MOUNTING CROSSBAR B, THEN LOCK IN PLACE WITH LOCKWASHER E AND LOCKNUT F.
4. SLIDE WIRES FROM FIXTURE THROUGH COLLAR RING J, COLLAR LOOP I, AND CEILING CANOPY H.
5. WIRE FIXTURE BY CONNECTING BLACK WIRE FROM SOCKET TO BLACK WIRE FROM SOURCE AND WHITE WIRE FROM SOCKET TO WHITE WIRE FROM SOURCE. STRIP APPROX. 4" OF INSULATION FROM GREEN GROUND WIRE G. THEN, CLOSE TO INSULATION, OR IF BARE COPPER WIRE IS SUPPLIED, LOOP WIRE AROUND GROUND SCREW ON MOUNTING CROSSBAR B AND CONNECT BARE COPPER WIRE OR GREEN GROUND WIRE FROM SOURCE TO END OF STRIPPED WIRE OR BARE COPPER WIRE.
6. SLIP CEILING CANOPY H OVER STUD D.
7. SCREW COLLAR LOOP INTO STUD D AND SECURE CEILING CANOPY H WITH COLLAR RING J.
8. ATTACH ONE END OF CHAIN K TO COLLAR LOOP I.
9. ATTACH OTHER END OF CHAIN K TO LOOP ON TOP OF FIXTURE.
10. ALL WIRING MUST BE ROUTED THRU CHAIN K TO INCOMING SUPPLY WIRE.



*NOTE: ITEM A SUPPLIED BY CONTRACTOR